

**NOTIFICATION OF THE PRESENCE OF ASBESTOS IN BUILDINGS AT CSU NORTHRIDGE
JANUARY 2012**

This notification is being provided pursuant to the requirements of California Health and Safety Code, Section 25915. As part of building renovation projects, a majority of the asbestos containing construction materials (ACM) have been removed from campus buildings. Despite these efforts, ACM still exist in some buildings. For your information, a list of building locations and a brief description of the materials, which are known to contain asbestos, can be found below.

ACMs were identified via surveys that may have included detailed building inspections, material sampling, and laboratory analysis. The sampling and laboratory procedures utilized in conducting these surveys included National Institute for Occupational Safety and Health (NIOSH) and Environmental Protection Agency (EPA) methods. ACMs pose no threat to your health unless the asbestos fibers become airborne due to deterioration, or as a result of damage. Therefore, it is important that proper work practices be followed to minimize the potential for disturbing asbestos-containing construction materials. Avoid touching asbestos materials on ceilings, pipes, and duct insulation. Do not drill holes, hang plants or other objects from walls or ceilings, which contain ACM. Do not disturb ACM when replacing light bulbs.

If you find ACM that has been damaged, immediately report the condition to Environmental Health and Safety at extension 2401. Do not disturb damaged ACM or asbestos debris. Only authorized and properly trained individuals may perform any work, which may disturb ACM.

BUILDING	LOCATION	SPECIFIC ASBESTOS CONTAINING MATERIALS
Bank Building	Telecom Room; Class 1	Floor tile and mastic
Black House	Room 4, 5; Attic; Roof	Floor tile and mastic; Duct insulation; Roof mastic and pipe
Bookstore Complex	Penthouse mechanical room; Various rooms	Chilled water (HVAC) pipe elbow, lagging and insulation; Floor mastic
Chicano Cultural Center	Roof	Roof mastic and roll
Child and Family Studies Lab School	Kitchen and Restroom; Windows	Floor tile and mastic; Putty
Cypress Hall	Mechanical rooms/maintenance access areas; Mech. Rm 281	Thermal pipe insulation; Tank (high temp) insulation
Eucalyptus Hall	Mechanical rooms/maintenance access areas	Thermal pipe insulation
Green House / Botanical Gardens	Windows / Roof	Putty; Weather stripping; Transite panels; Pipe lagging
Jacaranda Hall	North West mechanical room	Thermal pipe insulation
Jerome Richfield Hall	Mechanical rooms/maintenance access areas	Thermal pipe insulation
Live Oak Hall	Mechanical rooms/maintenance access areas	Thermal pipe insulation
Nautilus Fitness Center	Restroom/ Room 101	Floor tile and mastic, Wallboard/joint compound/plaster/mirror mastic
Nordhoff Hall	Mechanical rooms/maintenance access areas	Thermal pipe insulation
Nordhoff Hall	Mechanical room hot water tank; Orchestra pit	Tank (high temp) insulation; Heating hot water pipe insulation
Nordhoff Hall	Rooms 200, 220, 220A, 221	9x9 Floor tile and mastic
Oviatt Library	Chiller room and basement	Tank (high temp) insulation; Thermal pipe insulation; Floor tile and mastic
Redwood Hall	Mechanical rooms/maintenance access areas	Thermal pipe insulation
Santa Susana Hall	Rooms 102 /113 / 114	Floor tile and mastic
Sierra Hall	Mechanical rooms/maintenance access areas	Thermal pipe insulation; Floor tile and mastic
Sierra Tower	Mechanical rooms/maintenance access areas	Thermal pipe insulation

If you have any questions or wish to review the asbestos surveys and specific sampling procedures, please contact EH & S at extension 2401 during normal business hours.